	er ID 59832 2010 12:59:47 PM												Page 1
Revision ID:	D412-724-043 Head Rest Assembly, LH		A	Accept						Setup	Start Stop		
	6/11/2010 Start Q	ty: 1.00 2ty: 1.00) (1884) (1894) (1884) (1894)			Cust Ite Custom		į.			•		
Approvals:	Process Plan:	L	Date:	Tooling:			Date:		I	Run	Start Stop		
Sequence ID/ Work Center ID		ion		Set U Run I	p/ Hours	Tool I	D Too	l# Plan Code	Accept Qty	Rej Qty	7	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr					,		******	- Miles		!	****	
N/A 100 DC Document Control	Rev N/A DOCUME	NT CONTROL Memo If D412-724- PPP D412-72	043 is a W/O on it's own,□l	0.00 0.00 Photocopy b	luefile and o	create labels per	510	105/28	*	4	(B	G 10	106/28
110 Packaging Packaging	Pick Kit	Memo		0.00		!			10.5	<u> </u>	28-		:
120 QC Quality Control	QC4- 100%	% Inspect kits fo	or completeness	0.00	510	0/03/28		!	_X			•	

NOTE: Date & initial all entries

						!			"			
Work Orde						:						Page 2
Item ID: Revision ID:	D412-724-04	43		Accept					Setup	Start		
Item Name:	Head Rest Ass	sembly, LH								Stop		
Start Date: Required Date: Reference:	6/11/2010 6/25/2010	Start Qty: 1.00 Req'd Qty: 1.00	1811 1841 1851 1841 1841 1841		Cust Item 1 Customer:	(D:			a			1181 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Approvals:	Process Pla	n:	Date:	Tooling:	D:	ate:	- !		Run	Start		
	QC:		Date:	SPC (Y/N):		ate:				Stop		
Sequence ID/ Work Center II)	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Re Qt	۲	Reject Number	Insp. Stamp
Packaging Packaging		Packaging Memo Identify and possible to the control of the contr	pack for shipping as per n: □PPP	0.00 PPP D412-724- Rev:		!	ľ	1./	// U/	J7/	55	
140		QC21- Final Inspection -	Work Order Release	0.00		1				10	100	ha 26
QC Quality Control		Мето		0.00		1					[0]/	<u> 28 /X</u>

41007.28

Dart Aerospace Lt	td
-------------------	----

	-									1 4
W/O:			WC	RK ORDER CHAN	GES					۳ ر
DATE	STEP	PRO	OCEDURE CHA	NGE		Ву	Date	Q ₁	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									,	
						į			·	
			·							
Part No	•	PAR #:	Fault Cate	gory:	NCI	R: Yes	No DQ	\: <u> </u>	Date:	
		esolution:							Date: _	
NCR:			WORK ORDI	ER NON-CONFORM	IANCE	(NCR)			
DATE	STEP	Description of NC			ction B		Verific	ation	1 Approval	Approval
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector
								ĺ		
						1.				
		,						ı		
								-		
				-						

NOTE: Date & initial all entries

Picklist Print Page 1 Friday, June 11, 2010 12:59:53 PM Work Order ID: 59832 Parent Item: D412-724-043 Parent Item Name: Head Rest Assembly, LH Start Date: 6/11/2010 **Required Date: 6/25/2010** IPP Rev:A□04.09.08□New Issue□KJ/JLM Comments: Start Qty: 1.00 Required Qty: 1.00 Component Item ID/ Replacement Mfg/ Primary Bin Last Route Unit of Qty per Kit Total Qty on Qty Date Status Item Name Item ID Purch Item Location Seq ID Measure Location Hand Issued Qty Issued AN525-10R6 Purchased No 120 Each 232.0000 10 6.28. . Screw Location Loc Qty Loc Code ST325 232 113524 232 D3303-041 Manufactured 120 Each 1.0000 B59679 Head Rest Location Loc Qty Loc Code ST186 58274 D3304-043 Manufactured No 120 Each 11.0000 (79) 10.0.385 Tube Assembly Location Loc Oty Loc Code ST187 11 54445 11

Dart Ae	rospace L	td) C.
W/O:			WC	ORK ORDER CHANGE	ES				
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву	Date	ty	Approval Chief Eng / Prod Mgr	Approva QC Inspect
								:	
Part No		PAR #:						Date: _	
	Resc	olution:					<u> </u>	Date: _	
NCR:		,	WORK ORDE	R NON-CONFORMA	NCE (NCF	R)			
DATE	STEP	Description of NC		Corrective Action Section		Verificat	ion	Approval	Approva
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date			Chief Eng	QC Inspect
							·		
							ļ.,		

NOTE: Date & initial all entries

ICA Page 19 (20 blank) of 20

25.3 WEIGHT AND BALANCE

REFERENCE ONLY

There is negligible weight change associated with the installation of the Dart Head Rest.

25.4 PARTS LIST

		•			
QTY -011	QTY -041	QTY -043	QTY -044	Part Number	Description
Х		t		D412-724-011	Dart Head Rest Kit, for 205/212/412
2	Х			D412-724-041	Head Rest Assembly, Center
1		, X		D412-724-043	Head Rest Assembly, LH
1			Х	D412-724-044	Head Rest Assembly, RH
	1	1	1	D3303-041 /	Head Rest
	1			D3304-041	Tube Assembly
		1		D3304-043 /	Tube Assembly
			1	D3304-044	Tube Assembly
	4	4	4	AN525-10R6	Screw
_					

• COPYRIGHT © 2004 BY DART AEROSPACE LTD. •
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT. IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

25-00-00

Revision: 0

Page 3 (4 blank) of 4